



Legend

- | | | | | | | |
|----------------------|------------------------|-----------------------|-----------------|--------------------------------------|--|---------------------|
| Single Track Section | Typical Trail Sections | Mile Post | Crossing Signal | Property Marker | Field Identified Potential Vernal Pool | Deer Wintering Area |
| Dual Track Section | Normal Path Typical | Stone Monuments | Electrical Box | Miscellaneous Points | MEIFW Potential Vernal Pool | FLOODWAY |
| Bridge Crossing | Normal Fill Typical | Railroad Equipment | Signal Control | Concrete/Stone Wall | Wetland Boundary | FEMA 100-Yr Flood |
| | Ledge A Typical | Crossing Signal Gates | Switch Station | Fence | Rare, Endangered, Threatened, Species | Conserved Land |
| | Ledge B Typical | Crossing Sign | Other Trails | Areas of Ledge | Bald Eagle Nest Buffer | Town Boundary |
| | Extreme Fill Typical | | Culvert | Steep Slopes | Tidewater Mucket | 10' Contours |
| | | | | Existing Androscoggin Multi-Use Path | Inland Waterfowl & Wading Bird Habitat | |
| | | | | Potential Trail Connection | Tidal Waterfowl & Wading Bird Habitat | |



Sheet 21
**Merrymeeting Trail
Corridor Study**

Topsham to Gardiner Maine

March 2011



Legend

- | | | | | | | |
|------------------------|------------------------|-------------------------|-------------------|---|--|-----------------------|
| — Single Track Section | Typical Trail Sections | ● Mile Post | ✕ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | Normal Fill Typical | Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | ■ Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | Ledge A Typical | ✕ Crossing Signal Gates | ● Switch Station | — Fence | Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | Ledge B Typical | ⊗ Crossing Sign | ● Other Trails | — Areas of Ledge | 🦅 Bald Eagle Nest Buffer | — Streams |
| | Extreme Fill Typical | | ● Culvert | — Steep Slopes | 🦆 Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androscooggin Multi-Use Path | 🦆 Inland Waterfowl & Wading Bird Habitat | --- 10' Contours |
| | | | | — Potential Trail Connection | 🦆 Tidal Waterfowl & Wading Bird Habitat | |




Sheet 22

**Merrymeeting Trail
Corridor Study**

Topsham to Gardiner Maine

March 2011



Legend

- | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--------------------------|----------------------------|----------------------|-------------------------|--------------------------|--------------------|--------------------|------------------|----------------|---------------------|--------------------------|-------------------------|-----------------------|--------------------|------------------|--|--|--|--|-------------------------------|---|---|--------------------------|--|---|---|-----------------------|-----------------------|---------------------|-------------------|------------------|----------------|
| —+— Single Track Section | —+— Typical Trail Sections | ● Mile Post | ⬢ Stone Monuments | ⚡ Crossing Signal | ⚡ Electrical Box | ⚡ Signal Control | ⚡ Switch Station | ⚡ Other Trails | ⚡ Culvert | ⚡ Property Marker | ⚡ Miscellaneous Points | ⚡ Concrete/Stone Wall | ⚡ Fence | ⚡ Areas of Ledge | ⚡ Steep Slopes | ⚡ Existing Androscoogin Multi-Use Path | ⚡ Potential Trail Connection | ● Field Identified Potential Vernal Pool | ■ MEIFW Potential Vernal Pool | ■ Wetland Boundary | ■ Rare, Endangered, Threatened, Species | ■ Bald Eagle Nest Buffer | ■ Tidewater Mucket | ■ Inland Waterfowl & Wading Bird Habitat | ■ Tidal Waterfowl & Wading Bird Habitat | ■ Deer Wintering Area | ■ FLOODWAY | ■ FEMA 100-Yr Flood | ■ Conserved Land | ■ Town Boundary | ■ 10' Contours |
| —+— Dual Track Section | —+— Normal Path Typical | ⬢ Railroad Equipment | ⬢ Crossing Signal Gates | ⬢ Crossing Sign | ⬢ Signal Control | ⬢ Switch Station | ⬢ Other Trails | ⬢ Culvert | ⬢ Property Marker | ⬢ Miscellaneous Points | ⬢ Concrete/Stone Wall | ⬢ Fence | ⬢ Areas of Ledge | ⬢ Steep Slopes | ⬢ Existing Androscoogin Multi-Use Path | ⬢ Potential Trail Connection | ⬢ Field Identified Potential Vernal Pool | ⬢ MEIFW Potential Vernal Pool | ⬢ Wetland Boundary | ⬢ Rare, Endangered, Threatened, Species | ⬢ Bald Eagle Nest Buffer | ⬢ Tidewater Mucket | ⬢ Inland Waterfowl & Wading Bird Habitat | ⬢ Tidal Waterfowl & Wading Bird Habitat | ⬢ Deer Wintering Area | ⬢ FLOODWAY | ⬢ FEMA 100-Yr Flood | ⬢ Conserved Land | ⬢ Town Boundary | ⬢ 10' Contours | |
| —+— Bridge Crossing | —+— Normal Fill Typical | —+— Ledge A Typical | —+— Ledge B Typical | —+— Extreme Fill Typical | —+— Signal Control | —+— Switch Station | —+— Other Trails | —+— Culvert | —+— Property Marker | —+— Miscellaneous Points | —+— Concrete/Stone Wall | —+— Fence | —+— Areas of Ledge | —+— Steep Slopes | —+— Existing Androscoogin Multi-Use Path | —+— Potential Trail Connection | —+— Field Identified Potential Vernal Pool | —+— MEIFW Potential Vernal Pool | —+— Wetland Boundary | —+— Rare, Endangered, Threatened, Species | —+— Bald Eagle Nest Buffer | —+— Tidewater Mucket | —+— Inland Waterfowl & Wading Bird Habitat | —+— Tidal Waterfowl & Wading Bird Habitat | —+— Deer Wintering Area | —+— FLOODWAY | —+— FEMA 100-Yr Flood | —+— Conserved Land | —+— Town Boundary | —+— 10' Contours | |




Sheet 23

**Merrymeeting Trail
Corridor Study**


Topsham to Gardiner Maine

March 2011



Legend

- | | | | | | | |
|--------------------------|-----------------------|-------------------------|-------------------|---|--|-----------------------|
| —+— Single Track Section | — Normal Path Typical | ● Mile Post | ⚡ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | — Normal Fill Typical | ◇ Stone Monuments | ⚡ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | — Ledge A Typical | ⓧ Railroad Equipment | ⓧ Signal Control | — Concrete/Stone Wall | 🌿 Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | — Ledge B Typical | ⓧ Crossing Signal Gates | ⓧ Switch Station | — Fence | 🦅 Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| — Extreme Fill Typical | | ⓧ Crossing Sign | — Other Trails | — Areas of Ledge | 🦅 Bald Eagle Nest Buffer | — Streams |
| | | | ● Culvert | — Steep Slopes | 🦅 Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androscooggin Multi-Use Path | 🦅 Inland Waterfowl & Wading Bird Habitat | — 10' Contours |
| | | | | — Potential Trail Connection | 🦅 Tidal Waterfowl & Wading Bird Habitat | |





Legend

- | | | | | | | |
|------------------------|------------------------|-------------------------|-------------------|--|--|-----------------------|
| — Single Track Section | Typical Trail Sections | ● Mile Post | ✕ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | Normal Fill Typical | Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | 🌿 Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | Ledge A Typical | ✕ Crossing Signal Gates | Ⓢ Switch Station | — Fence | Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | Ledge B Typical | ⊗ Crossing Sign | — Other Trails | — Areas of Ledge | 🦅 Bald Eagle Nest Buffer | — Streams |
| | Extreme Fill Typical | | ● Culvert | — Steep Slopes | 🐊 Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androscoogin Multi-Use Path | 🦆 Inland Waterfowl & Wading Bird Habitat | — 10' Contours |
| | | | | — Potential Trail Connection | 🦆 Tidal Waterfowl & Wading Bird Habitat | |






Source: \unh-bad\projects\62018_00\GIS\Project\Mapshere.mxd

Legend

- | | | | | | | |
|----------------------|------------------------|-----------------------|-----------------|---------------------------------------|--|---------------------|
| Single Track Section | Typical Trail Sections | Mile Post | Crossing Signal | Property Marker | Field Identified Potential Vernal Pool | Deer Wintering Area |
| Dual Track Section | Normal Path Typical | Stone Monuments | Electrical Box | Miscellaneous Points | MEIFW Potential Vernal Pool | FLOODWAY |
| Bridge Crossing | Normal Fill Typical | Railroad Equipment | Signal Control | Concrete/Stone Wall | Wetland Boundary | FEMA 100-Yr Flood |
| | Ledge A Typical | Crossing Signal Gates | Switch Station | Fence | Rare, Endangered, Threatened, Species | Conserved Land |
| | Ledge B Typical | Crossing Sign | Other Trails | Areas of Ledge | Bald Eagle Nest Buffer | Streams |
| | Extreme Fill Typical | | Culvert | Steep Slopes | Tidewater Mucket | Town Boundary |
| | | | | Existing Androscooggin Multi-Use Path | Inland Waterfowl & Wading Bird Habitat | 10' Contours |
| | | | | Potential Trail Connection | Tidal Waterfowl & Wading Bird Habitat | |



Sheet 26
**Merrymeeting Trail
Corridor Study**

Topsham to Gardiner Maine

March 2011



Legend

- | | | | | | | |
|------------------------|------------------------|-------------------------|-------------------|--|--|-----------------------|
| — Single Track Section | Typical Trail Sections | ● Mile Post | ✕ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | Normal Fill Typical | Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | ■ Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | Ledge A Typical | ✕ Crossing Signal Gates | ● Switch Station | — Fence | Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | Ledge B Typical | ⊗ Crossing Sign | — Other Trails | — Areas of Ledge | 🦅 Bald Eagle Nest Buffer | — Streams |
| | Extreme Fill Typical | | ● Culvert | — Steep Slopes | 🦆 Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androskoggin Multi-Use Path | 🦆 Inland Waterfowl & Wading Bird Habitat | --- 10' Contours |
| | | | | — Potential Trail Connection | 🦆 Tidal Waterfowl & Wading Bird Habitat | |



Sheet 27
**Merrymeeting Trail
Corridor Study**

Topsham to Gardiner Maine

March 2011



Source: Unpublished project 5/20/08, 00/05/08 Project Mapshere.mxd

Legend

- | | | | | | | |
|------------------------|--------------------------|-------------------------|------------------------------|--|--|-----------------------|
| — Single Track Section | — Typical Trail Sections | ● Mile Post | ⛶ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| — Dual Track Section | — Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | — Normal Fill Typical | — Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | ■ Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | — Ledge A Typical | ✕ Crossing Signal Gates | ■ Switch Station | — Fence | ■ Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | — Ledge B Typical | ⊗ Crossing Sign | — Other Trails | — Areas of Ledge | ■ Bald Eagle Nest Buffer | — Streams |
| | — Extreme Fill Typical | ● Culvert | — Steep Slopes | — Existing Androskoggin Multi-Use Path | ■ Tidewater Mucket | ▨ Town Boundary |
| | | | — Potential Trail Connection | ■ Inland Waterfowl & Wading Bird Habitat | ■ Tidal Waterfowl & Wading Bird Habitat | — 10' Contours |






Source: \unh\hdd\projects\62088_00\GIS\Project Maps\sheet29.mxd

Legend


- | | | | | | | |
|------------------------|------------------------|-------------------------|-------------------|--|--|-----------------------|
| — Single Track Section | Typical Trail Sections | ● Mile Post | ⚡ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | Normal Fill Typical | Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | 🌿 Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | Ledge A Typical | ✕ Crossing Signal Gates | Ⓢ Switch Station | — Fence | Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | Ledge B Typical | ⊗ Crossing Sign | — Other Trails | — Areas of Ledge | 🦅 Bald Eagle Nest Buffer | — Streams |
| | Extreme Fill Typical | | ● Culvert | — Steep Slopes | 🐟 Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androskoggin Multi-Use Path | 🦆 Inland Waterfowl & Wading Bird Habitat | — 10' Contours |
| | | | | — Potential Trail Connection | 🦆 Tidal Waterfowl & Wading Bird Habitat | |






Legend


- | | | | | | | |
|------------------------|--------------------------|-------------------------|------------------------------|--|--|-----------------------|
| — Single Track Section | — Typical Trail Sections | ● Mile Post | ⛶ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| — Dual Track Section | — Normal Path Typical | ◇ Stone Monuments | ⚡ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | — Normal Fill Typical | ⛶ Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | 🌿 Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | — Ledge A Typical | ⛶ Crossing Signal Gates | Ⓢ Switch Station | — Fence | Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | — Ledge B Typical | ⛶ Crossing Sign | — Other Trails | — Areas of Ledge | 🦅 Bald Eagle Nest Buffer | — Streams |
| | — Extreme Fill Typical | ● Culvert | — Steep Slopes | — Existing Androskoggin Multi-Use Path | 🐟 Tidewater Mucket | ▨ Town Boundary |
| | | | — Potential Trail Connection | — Inland Waterfowl & Wading Bird Habitat | 🦅 Tidal Waterfowl & Wading Bird Habitat | — 10' Contours |





Legend

- | | | | | | | |
|------------------------|--------------------------|-------------------------|-------------------|---|--|-----------------------|
| — Single Track Section | — Typical Trail Sections | ● Mile Post | ⚡ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | — Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | — Normal Fill Typical | ⚡ Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | 🌿 Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | — Ledge A Typical | ✕ Crossing Signal Gates | Ⓢ Switch Station | — Fence | Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | — Ledge B Typical | ⊗ Crossing Sign | — Other Trails | — Areas of Ledge | 🦅 Bald Eagle Nest Buffer | — Streams |
| | — Extreme Fill Typical | | ● Culvert | — Steep Slopes | 🐟 Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androscooggin Multi-Use Path | 🦉 Inland Waterfowl & Wading Bird Habitat | — 10' Contours |
| | | | | — Potential Trail Connection | 🦉 Tidal Waterfowl & Wading Bird Habitat | |






Source: \unh\hdp\projects\562018_00\GIS\Project Maps\sheet33.mxd

Legend

- | | | | | | | |
|------------------------|--------------------------|-------------------------|-------------------|--|--|-----------------------|
| — Single Track Section | — Typical Trail Sections | ● Mile Post | ⚡ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| — Dual Track Section | — Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | — Normal Fill Typical | Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | ■ Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | — Ledge A Typical | ✕ Crossing Signal Gates | ■ Switch Station | — Fence | Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | — Ledge B Typical | ⊗ Crossing Sign | — Other Trails | — Areas of Ledge | ■ Bald Eagle Nest Buffer | — Streams |
| | — Extreme Fill Typical | | ● Culvert | — Steep Slopes | ■ Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androskoggin Multi-Use Path | ■ Inland Waterfowl & Wading Bird Habitat | — 10' Contours |
| | | | | — Potential Trail Connection | ■ Tidal Waterfowl & Wading Bird Habitat | |





Legend

- | | | | | | | |
|--------------------------|----------------------------|-------------------------|-------------------|---|--|-----------------------|
| —+— Single Track Section | —+— Typical Trail Sections | ● Mile Post | ⚡ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | — Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | — Normal Fill Typical | ⚡ Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | — Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | — Ledge A Typical | ✕ Crossing Signal Gates | Ⓢ Switch Station | — Fence | — Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | — Ledge B Typical | ⊗ Crossing Sign | — Other Trails | — Areas of Ledge | — Bald Eagle Nest Buffer | — Streams |
| | — Extreme Fill Typical | | ● Culvert | — Steep Slopes | — Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androscooggin Multi-Use Path | — Inland Waterfowl & Wading Bird Habitat | — 10' Contours |
| | | | | — Potential Trail Connection | — Tidal Waterfowl & Wading Bird Habitat | |




Sheet 34

**Merrymeeting Trail
Corridor Study**

Topsham to Gardiner Maine

March 2011



Source: Unbound projects\62018_00\GIS\Project Maps\Sheet 36.mxd

Sheet 36

Merrymeeting Trail Corridor Study

Topsham to Gardiner Maine

March 2011

Legend

Single Track Section

Dual Track Section

Bridge Crossing

Normal Path Typical

Normal Fill Typical

Ledge A Typical

Ledge B Typical

Extreme Fill Typical

Mile Post

Stone Monuments

Railroad Equipment

Crossing Signal Gates

Crossing Sign

Culvert

Crossing Signal

Electrical Box

Signal Control

Switch Station

Other Trails

Property Marker

Miscellaneous Points

Concrete/Stone Wall

Fence

Areas of Ledge

Steep Slopes

Potential Trail Connection

Field Identified Potential Vernal Pool

MEIFW Potential Vernal Pool

Wetland Boundary

Rare, Endangered, Threatened, Species

Bald Eagle Nest Buffer

Tidewater Mucket

Inland Waterfowl & Wading Bird Habitat

Tidal Waterfowl & Wading Bird Habitat

Deer Wintering Area

FLOODWAY

FEMA 100-Yr Flood

Conserved Land

Streams

Town Boundary

10' Contours

0

200

400 Feet

Sheet 36

Merrymeeting Trail Corridor Study

Topsham to Gardiner Maine

March 2011

Legend

Single Track Section

Dual Track Section

Bridge Crossing

Normal Path Typical

Normal Fill Typical

Ledge A Typical

Ledge B Typical

Extreme Fill Typical

Mile Post

Stone Monuments

Railroad Equipment

Crossing Signal Gates

Crossing Sign

Culvert

Crossing Signal

Electrical Box

Signal Control

Switch Station

Other Trails

Property Marker

Miscellaneous Points

Concrete/Stone Wall

Fence

Areas of Ledge

Steep Slopes

Potential Trail Connection

Field Identified Potential Vernal Pool

MEIFW Potential Vernal Pool

Wetland Boundary

Rare, Endangered, Threatened, Species

Bald Eagle Nest Buffer

Tidewater Mucket

Inland Waterfowl & Wading Bird Habitat

Tidal Waterfowl & Wading Bird Habitat

Deer Wintering Area

FLOODWAY

FEMA 100-Yr Flood

Conserved Land

Streams

Town Boundary

10' Contours

0

200

400 Feet

Sheet 36

Merrymeeting Trail Corridor Study

Topsham to Gardiner Maine

March 2011

Legend

Single Track Section

Dual Track Section

Bridge Crossing

Normal Path Typical

Normal Fill Typical

Ledge A Typical

Ledge B Typical

Extreme Fill Typical

Mile Post

Stone Monuments

Railroad Equipment

Crossing Signal Gates

Crossing Sign

Culvert

Crossing Signal

Electrical Box

Signal Control

Switch Station

Other Trails

Property Marker

Miscellaneous Points

Concrete/Stone Wall

Fence

Areas of Ledge

Steep Slopes

Potential Trail Connection

Field Identified Potential Vernal Pool

MEIFW Potential Vernal Pool

Wetland Boundary

Rare, Endangered, Threatened, Species

Bald Eagle Nest Buffer

Tidewater Mucket

Inland Waterfowl & Wading Bird Habitat

Tidal Waterfowl & Wading Bird Habitat

Deer Wintering Area

FLOODWAY

FEMA 100-Yr Flood

Conserved Land

Streams

Town Boundary

10' Contours

0

200

400 Feet

Sheet 36

Merrymeeting Trail Corridor Study

Topsham to Gardiner Maine

March 2011

Legend

Single Track Section

Dual Track Section

Bridge Crossing

Normal Path Typical

Normal Fill Typical

Ledge A Typical

Ledge B Typical

Extreme Fill Typical

Mile Post

Stone Monuments

Railroad Equipment

Crossing Signal Gates

Crossing Sign

Culvert

Crossing Signal

Electrical Box

Signal Control

Switch Station

Other Trails

Property Marker

Miscellaneous Points

Concrete/Stone Wall

Fence

Areas of Ledge

Steep Slopes

Potential Trail Connection

Field Identified Potential Vernal Pool

MEIFW Potential Vernal Pool

Wetland Boundary

Rare, Endangered, Threatened, Species

Bald Eagle Nest Buffer

Tidewater Mucket

Inland Waterfowl & Wading Bird Habitat

Tidal Waterfowl & Wading Bird Habitat

Deer Wintering Area

FLOODWAY

FEMA 100-Yr Flood

Conserved Land

Streams

Town Boundary

10' Contours

0

200

400 Feet

Sheet 36

Merrymeeting Trail Corridor Study

Topsham to Gardiner Maine

March 2011

Legend

Single Track Section

Dual Track Section

Bridge Crossing

Normal Path Typical

Normal Fill Typical

Ledge A Typical

Ledge B Typical

Extreme Fill Typical

Mile Post

Stone Monuments

Railroad Equipment

Crossing Signal Gates

Crossing Sign

Culvert

Crossing Signal

Electrical Box

Signal Control

Switch Station

Other Trails

Property Marker

Miscellaneous Points

Concrete/Stone Wall

Fence

Areas of Ledge

Steep Slopes

Potential Trail Connection

Field Identified Potential Vernal Pool

MEIFW Potential Vernal Pool

Wetland Boundary

Rare, Endangered, Threatened, Species

Bald Eagle Nest Buffer

Tidewater Mucket

Inland Waterfowl & Wading Bird Habitat

Tidal Waterfowl & Wading Bird Habitat

Deer Wintering Area

FLOODWAY

FEMA 100-Yr Flood

Conserved Land

Streams

Town Boundary

10' Contours

0

200

400 Feet

Sheet 36

Merrymeeting Trail Corridor Study

Topsham to Gardiner Maine

March 2011

Legend

Single Track Section

Dual Track Section

Bridge Crossing

Normal Path Typical

Normal Fill Typical

Ledge A Typical

Ledge B Typical

Extreme Fill Typical

Mile Post

Stone Monuments

Railroad Equipment

Crossing Signal Gates

Crossing Sign

Culvert

Crossing Signal

Electrical Box

Signal Control

Switch Station

Other Trails

Property Marker

Miscellaneous Points

Concrete/Stone Wall

Fence

Areas of Ledge

Steep Slopes

Potential Trail Connection

Field Identified Potential Vernal Pool

MEIFW Potential Vernal Pool

Wetland Boundary

Rare, Endangered, Threatened, Species

Bald Eagle Nest Buffer

Tidewater Mucket

Inland Waterfowl & Wading Bird Habitat

Tidal Waterfowl & Wading Bird Habitat

Deer Wintering Area

FLOODWAY

FEMA 100-Yr Flood

Conserved Land

Streams

Town Boundary

10' Contours

0

200

400 Feet

Sheet 36

Merrymeeting Trail Corridor Study

Topsham to Gardiner Maine

March 2011

Legend

Single Track Section

Dual Track Section

Bridge Crossing

Normal Path Typical

Normal Fill Typical

Ledge A Typical

Ledge B Typical

Extreme Fill Typical

Mile Post

Stone Monuments

Railroad Equipment

Crossing Signal Gates

Crossing Sign

Culvert

Crossing Signal

Electrical Box

Signal Control

Switch Station

Other Trails

Property Marker

Miscellaneous Points

Concrete/Stone Wall

Fence

Areas of Ledge

Steep Slopes

Potential Trail Connection

Field Identified Potential Vernal Pool

MEIFW Potential Vernal Pool

Wetland Boundary

Rare, Endangered, Threatened, Species

Bald Eagle Nest Buffer

Tidewater Mucket

Inland Waterfowl & Wading Bird Habitat

Tidal Waterfowl & Wading Bird Habitat

Deer Wintering Area

FLOODWAY

FEMA 100-Yr Flood

Conserved Land

Streams

Town Boundary

10' Contours

0

200

400 Feet

Sheet 36

Merrymeeting Trail Corridor Study

Topsham to Gardiner Maine

March 2011


Legend

Single Track Section



Legend


- | | | | | | | |
|--------------------------|----------------------------|-------------------------|-------------------|---|--|-----------------------|
| —+— Single Track Section | —+— Typical Trail Sections | ● Mile Post | ⚡ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | — Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | — Normal Fill Typical | ⚡ Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | ■ Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | — Ledge A Typical | ✕ Crossing Signal Gates | Ⓢ Switch Station | — Fence | 🦅 Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | — Ledge B Typical | ⊗ Crossing Sign | — Other Trails | — Areas of Ledge | 🦅 Bald Eagle Nest Buffer | — Streams |
| | — Extreme Fill Typical | | ● Culvert | — Steep Slopes | 🦉 Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androscooggin Multi-Use Path | 🦉 Inland Waterfowl & Wading Bird Habitat | — 10' Contours |
| | | | | — Potential Trail Connection | 🦉 Tidal Waterfowl & Wading Bird Habitat | |





Legend

- | | | | | | | |
|--------------------------|------------------------|-------------------------|-------------------|--|--|-----------------------|
| —+— Single Track Section | — Normal Path Typical | ● Mile Post | ⚡ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | — Normal Fill Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | — Ledge A Typical | ⛔ Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | — Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | — Ledge B Typical | ⛔ Crossing Signal Gates | Ⓢ Switch Station | — Fence | Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | — Extreme Fill Typical | ⛔ Crossing Sign | — Other Trails | — Areas of Ledge | — Bald Eagle Nest Buffer | — Streams |
| | | | ● Culvert | — Steep Slopes | — Tidewater Mucket | ▨ Town Boundary |
| | | | | — Existing Androscoggin Multi-Use Path | — Inland Waterfowl & Wading Bird Habitat | — 10' Contours |
| | | | | — Potential Trail Connection | — Tidal Waterfowl & Wading Bird Habitat | |





Legend

- | | | | | | | |
|------------------------|--------------------------|-------------------------|-------------------|--|--|--|
| — Single Track Section | — Typical Trail Sections | ● Mile Post | ⚡ Crossing Signal | ▲ Property Marker | ● Field Identified Potential Vernal Pool | 🦌 Deer Wintering Area |
| == Dual Track Section | — Normal Path Typical | ◇ Stone Monuments | ■ Electrical Box | ▲ Miscellaneous Points | ■ MEIFW Potential Vernal Pool | FLOODWAY |
| — Bridge Crossing | — Normal Fill Typical | ⚡ Railroad Equipment | ■ Signal Control | — Concrete/Stone Wall | ■ Wetland Boundary | ▨ FEMA 100-Yr Flood |
| | — Ledge A Typical | ⚡ Crossing Signal Gates | Ⓢ Switch Station | — Fence | Rare, Endangered, Threatened, Species | ▨ Conserved Land |
| | — Ledge B Typical | ⊗ Crossing Sign | — Other Trails | — Areas of Ledge | — Bald Eagle Nest Buffer | — Town Boundary |
| | — Extreme Fill Typical | | ● Culvert | — Steep Slopes | — Tidewater Mucket | — Streams |
| | | | | — Existing Androscoggin Multi-Use Path | — Inland Waterfowl & Wading Bird Habitat | — Inland Waterfowl & Wading Bird Habitat |
| | | | | — Potential Trail Connection | — Tidal Waterfowl & Wading Bird Habitat | — Tidal Waterfowl & Wading Bird Habitat |

